

TECHNICAL INFORMATION

TYPE NO	FB 55	TYPE	Coffee vending machines	T.I.-NO	02/2003
SERIAL NUMBERS	All refurbished and new FB55 VMC-boards since September 1st, 2002			ISSUED BY	Documentation/Wittenborg Odense
AFFECTED				ISSUED FOR (X):	
SUBJECT	Refurbished VMC boards and new VMC board 47180501 plus updated Diagram 35181900			Action	
				Information	X

COMPONENTS CONCERNED

Article No	Designation
47180501	VMC Board FB55
47180590R	VMC Board 55 refurbished
47180591R	VMC Board 55 refurbished
35181900	Wiring Diagram (Block Diagram)

MODIFICATION

- Since September 1st, 2002 all FB 55 VMC-boards have been fitted with the Add-on PCB, securing settings in the machine. See FB55 WA 01/01 and FB 55 08/00.

This modification covers the new board, 47180501 as well as the refurbished boards 47180590R and 47180591R.



The circle highlights the modification to the boards.

- Wring diagram (Block diagram) 35181900 has been updated, see next page.

REASON

- Machines originally fitted with the boards 47180500 and 47180501 can be fitted with the latest versions of the board 47180503, however, this modification implies rebuilding of the machine.
Replacing the board 47180500 with the board 47180590R or replacing the board 47180501 with the board 47180591R only implies exchange of these boards in the machines.

11.08.03	Grete Jensen	11.08.03	Jes Erik Rasmussen
DATE:	PRODUCED BY:	DATE:	CHECKED BY:

